

**DEFENSE SUPPLY CENTER, COLUMBUS
STATUS REPORT ON
FSC 5905 RESISTORS
October 2002**

The following specifications and standards have been approved and dated:

Specification	Description	Date	Notes
87026	Network 3 PIN, fixed film	14 May 02	Derating curve added
02005 (NEW)	1/2" Trimmer	3 Oct 02	Replaces RJR28.
MIL-DTL-6749	Rheostats: Aircraft Power	23 Aug 02	Incorporate AN3155 into spec
MIL-DTL-7790	Thermocouple Lead Spool	6 May 02	Incorporate AN5534 into spec
A-A-55156, -55157, -55158, & -55159	Fixed, Wire wound, Power type	10 Jun 02	Cancel
A-A-59715 (NEW)	Fixed and Adjustable, Wire wound, Power type	10 Jun 02	NEW - Replaces A-A-55156, -55157, -55158 and -55159
02001 (NEW)	Fixed, Film, Precision, Chip 1/8 Watt Style 2012	18 Jul 02	MIL-R-122 part in a chip
MIL-PRF-55182 & slash sheet	Fixed, Film, Precision	26 Sep 02	Validate and update to current DoD policies.
MIL-PRF-12934/37	Variable, Wire wound, Precision, Style 2RR3100	3 Oct 02	NEW

The following specifications/drawings are being revised, created, or proposed for inactivation/cancellation:

Specification	Description	Justification
MIL-PRF-23648 & slash sheet	Thermistors	Validate and update to current DoD policies.
A-A-55517 & slash sheets	Fixed, Carbon, Film	Validate and update to current DoD policies.
A-A-55534 & slash sheets	Fixed, Wire wound or Metal Element Chip	Add characteristics for tin & tin/lead finish. New source of supply.
02008	Film, Chip, Low & High values, Styles 1206	NEW
02009	Film, Flip Chip, Ultra Precision, Styles 1206	NEW
02010	Film, Chip, Values less than 1 ohm.	NEW

Points of Contact for FSC 5905:

Andrew Ernst - Phone: 614-692-0552
Dennis Cross - Phone: 614-692-0553
Jesus Garcia - Phone: 614-692-8754

E-mail: resistor@dsc.dla.mil

Defense Supply Center, Columbus
DSCC-VAT
Post Office Box 3990
Columbus, OH 43216-5000
Fax: 614-692-6939

Internet Address:
DSCC-VA - Document Control Unit
<http://www.dsc.dla.mil/v/va/index.html>
DSCC-VAT - Electronics Components Team
<http://www.dsc.dla.mil/v/va/vat/index.html>